EAF Mobile Facilities (Ile Shima Island)

QHR205

(please note: This is a MALS-36 MF CSC failure, beyond Repair capability.)

ISO corners delaminating and coliflowering.



ISO corners delaminating and coliflowering.

QHR205

Bottom side rail damage/deteriorated by corrosion.



Cracked ISO corner due to corrosion damage.

QHR205

Forklift pockets deteriorated beyond repair capability. Brittle to the touch.
(All forklift pockets are in the same

QHR171

(please note: This is a NADEP MF CSC failure, beyond Repair capability.)





ISO Corner Coliflowering.

QHR171



Corrosion damage on side rail (structural member).



ISO Corner Coliflowering.

QHR171



ISO Corner Coliflowering.

QHR171/QHR205

Please note: More pictures are available if needed.